


300

300 011, 012 (10).



300-052

	100 , Pt100, Pt500		3 155	0 160

d=4	d=5	d=6
8	12	16

10 . 12 18 10 ;

300

L: 80, 100, 120, 160 .

ℓ : 500, 800, 1000, 1600, 2000, 2500, 3150 .

				d,	L,		ℓ ,	
					min	max	min	max
300	-052	100	4, 4	5.0, 6.0	80	160	500	3150
			2					1000
	-065	Pt100	4, 4	4.0				3150
	-052		2	5.0, 6.0				1000
	-065	Pt500	4, 4, 2	4.0				3150
	-052			5.0, 6.0				

*

300-052 - - - - d - L/ ℓ

300-052 - Pt100 - B2 - 6 - 80/1000 .

300-052

Pt100,

6

80

1000